

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

25X1

SECRET/CONTROL - U.S. OFFICIALS ONLY
SECURITY INFORMATION

COUNTRY	East Germany	REPORT	
SUBJECT	Unfulfilled Orders for Electrical Equipment for Soviet Satellites from East German Industrial Installations	DATE DISTR.	30 April 1953 25X1
DATE OF INFO.		NO. OF PAGES	2
PLACE ACQUIRED		REQUIREMENT	
		REFERENCES	

25X1

This is UNEVALUATED Information

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.
THE APPRAISAL OF CONTENT IS TENTATIVE.
(FOR KEY SEE REVERSE)

1. The following list indicates the type of material on order for delivery to Czechoslovakia, Poland, Hungary, Rumania, Bulgaria, and China, as well as shortages and other difficulties that have caused delay in the deliveries. Individual firms are not listed.

25X1

Serial	Item	Number on Order	Delivered to 1 October 1952	Reason for failure to deliver.
<u>A. Czechoslovakia</u>				
1.	Measuring instruments	4	Nil	Lack of casings and synchronized motors.
2.	Thermal transformers	400	225	Lack of platinum wire
3.	Electrical equipment	1	Nil	Lack of differential valves and transformers
4.	Current rectifiers	2	-	Jet rectifiers not delivered (Reparation order priority)
<u>B. Poland</u>				
5.	Measuring instruments	500	50	Owing to priority reparation orders not delivered
6.	Excess A/C current relays	188	Nil	Lack of bimetals

SECRET/CONTROL - U.S. OFFICIALS ONLY

25 YEAR RE-REVIEW

STATE	x	ARMY	x	NAVY	x	AIR	x	FBI		AEC		ORR	Ev	x		
-------	---	------	---	------	---	-----	---	-----	--	-----	--	-----	----	---	--	--

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

514

SECRET/CONTROL - U.S. OFFICIALS ONLY

- 2 -

Serial	Item	Number on Order	Delivered up to 1 October 1952	Reason for failure to deliver
7	Excess A/C current relays	195	11	Delayed delivery of sub-contracts.
8	" " " "	1132	690	Lack of tubes
9	" " " "	190	73	Lack of bimetals
C. <u>Hungary</u>				
10	Measuring instruments	457	408	Lack of cases and shafts
11	" "	641	121	Sub-contractors failure to deliver parts
12	" "	337	231	Lack of caps and base plates
13	Accelerated cut-outs	15	N11	Lack of copper wire
D. <u>Rumania</u>				
14	Excess current time relays	50	42	Lack of bimetals.
E. <u>Bulgaria</u>				
15	Measuring instruments	207	198	Reparation order priority
16	" "	60	20	Lack of casings and shaft terminals
17	Relays	4	1	Lack of materials
F. <u>China</u>				
18	Measuring instruments	266	185	Shaft terminals allo- cated to priority repa- ration orders
19	" "	128	120	Lack of casings and base plates.
20	Relays	60	N11	Lack of materials
21	Watt/hour meters	7,800	2,500	Lack of measuring transformers
22	" " "	4,600	4,200	Lack of measuring transformers.

SECRET/CONTROL - U.S. OFFICIALS ONLY